

LC and LH, MS Military Designations to Dialight Part Numbers

MILITARY SPECIFICATION:

MIL-DTL-3661C-Lampholders, Indicator Lights, Indicator-Light Housings, Indicator-Light Lenses

| <u>MILITARY DESIGNATION</u> | <u>DIALIGHT PART NO.</u> | <u>MILITARY DESIGNATION</u> | <u>DIALIGHT PART NO.</u> | <u>MILITARY DESIGNATION</u> | <u>DIALIGHT PART NO.</u> |
|-----------------------------|--------------------------|-----------------------------|--------------------------|-----------------------------|--------------------------|
| LC11BN2 | 178-0334-500 | LC17RN3 | *203-0131-203 | LC23GN3 | 209-0132-203 |
| LC11BT2 | 178-0374-500 | LC17WT3 | *203-0135-203 | LC23RD3 | 209-0111-203 |
| LC11CN2 | *178-0337-500 | LC17YD3 | 203-0113-203 | LC23RN3 | *209-0131-203 |
| LC11GN2 | 178-0332-500 | LC17YN3 | *203-0133-203 | LC23WT3 | *209-0135-203 |
| LC11GT2 | 178-0372-500 | LC18BD3 | 204-0114-203 | LC23YD3 | 209-0113-203 |
| LC11RN2 | *178-0331-500 | LC18BN3 | 204-0134-203 | LC23YN3 | *209-0133-203 |
| LC11RT2 | 178-0371-500 | LC18CD3 | 204-0117-203 | LC24BD3 | 210-0114-203 |
| LC11WT2 | 178-0375-500 | LC18CN3 | *204-0137-203 | LC24BN3 | 210-0134-203 |
| LC11YN2 | *178-0333-500 | LC18GD3 | 204-0112-203 | LC24CD3 | 210-0117-203 |
| LC11YT2 | 178-0373-500 | LC18GN3 | 204-0132-203 | LC24CN3 | *210-0137-203 |
| LC12BN2 | 162-0934 | LC18RD3 | 204-0111-203 | LC24GD3 | 210-0112-203 |
| LC12BT2 | 162-0974 | LC18RN3 | *204-0131-203 | LC24GN3 | 210-0132-203 |
| LC12CN2 | *162-0937 | LC18YD3 | 204-0113-203 | LC24RD3 | 210-0111-203 |
| LC12GN2 | 162-0932 | LC18YN3 | *204-0133-203 | LC24RN3 | *210-0131-203 |
| LC12GT2 | 162-0972 | LC19BD3 | 169-1114-203 | LC24WT3 | *210-0135-203 |
| LC12RN2 | *162-0931 | LC19BN3 | 169-1134-203 | LC24YD3 | 210-0113-203 |
| LC12RT2 | 162-0971 | LC19CD3 | 169-1117-203 | LC24YN3 | *210-0133-203 |
| LC12WT2 | 162-0975 | LC19CN3 | *169-1137-203 | LC25BN2 | 239-0334-500 |
| LC12YN2 | *162-0933 | LC19GD3 | 169-1112-203 | LC25BT2 | 239-0374-500 |
| LC12YT2 | 162-0973 | LC19GN3 | 169-1132-203 | LC25CN2 | *239-0337-500 |
| LC13CN2 | *137-0937 | LC19RD3 | 169-1111-203 | LC25GN2 | 239-0332-500 |
| LC13RN2 | *137-0931 | LC19RN3 | *169-1131-203 | LC25GT2 | 239-0372-500 |
| LC13WT2 | *137-0935 | LC19WT3 | *169-1135-203 | LC25RN2 | *239-0331-500 |
| LC13YN2 | *137-0933 | LC19YD3 | 169-1113-203 | LC25RT2 | 239-0371-500 |
| LC14BD3 | 081-0114-203 | LC19YN3 | *169-1133-203 | LC25WT2 | 239-0375-500 |
| LC14BN3 | 081-0134-203 | LC20BN3 | 169-1194-203 | LC25YN2 | *239-0333-500 |
| LC14CD3 | 081-0117-203 | LC20CN3 | *169-1197-203 | LC25YT2 | 239-0373-500 |
| LC14CN3 | *081-0137-203 | LC20GN3 | 169-1192-203 | LC29BN2 | 162-1434 |
| LC14GD3 | 081-0112-203 | LC20RN3 | *169-1191-203 | LC29BT2 | 162-1474 |
| LC14GN3 | 081-0132-203 | LC20WT3 | *169-1195-203 | LC29CN2 | *162-1437 |
| LC14RD3 | 081-0111-203 | LC20YN3 | *169-1193-203 | LC29GN2 | 162-1432 |
| LC14RN3 | *081-0131-203 | LC21BD3 | 051-0114-203 | LC29GT2 | 162-1472 |
| LC14WT3 | *081-0135-203 | LC21BN3 | 051-0134-203 | LC29RN2 | *162-1431 |
| LC14YD3 | 081-0113-203 | LC21CD3 | 051-0117-203 | LC29RT2 | 162-1471 |
| LC14YN3 | *081-0133-203 | LC21CN3 | *051-0137-203 | LC29WT2 | 162-1475 |
| LC15BD3 | 026-1114-203 | LC21GD3 | 051-0112-203 | LC29YN2 | *162-1433 |
| LC15BN3 | 026-1134-203 | LC21GN3 | 051-0132-203 | LC29YT2 | 162-1473 |
| LC15CN3 | *026-1137-203 | LC21RD3 | 051-0111-203 | LC30BN3 | 250-3534-500 |
| LC15GD3 | 026-1112-203 | LC21RN3 | *051-0131-203 | LC30GN3 | 250-3532-500 |
| LC15GN3 | 026-1132-203 | LC21WT3 | *051-0135-203 | LC30RN3 | 250-3531-500 |
| LC15RD3 | 026-1111-203 | LC21YD3 | 051-0113-203 | LC30WT3 | 250-3535-500 |
| LC15RN3 | *026-1131-203 | LC21YN3 | *051-0133-203 | LC30YN3 | 250-3533-500 |
| LC15WT3 | *026-1135-203 | LC22BD3 | 080-0514-203 | LC32BT2 | 250-1474-500 |
| LC15YD3 | 026-1113-203 | LC22BN3 | 080-0534-203 | LC32GT2 | 250-1472-500 |
| LC15YN3 | *026-1133-203 | LC22CD3 | 080-0517-203 | LC32RT2 | 250-1471-500 |
| LC16BN3 | 026-1194-203 | LC22CN3 | *080-0537-203 | LC32WT2 | 250-1475-500 |
| LC16CN3 | *026-1197-203 | LC22GD3 | 080-0512-203 | LC32YT2 | 250-1473-500 |
| LC16GN3 | 026-1192-203 | LC22GN3 | 080-0532-203 | LC33CN2 | *130-0937-003 |
| LC16RN3 | *026-1191-203 | LC22RD3 | 080-0511-203 | LC33RN2 | *130-0931-003 |
| LC16WT3 | *026-1195-203 | LC22RN3 | *080-0531-203 | LC33WT2 | *130-0935-003 |
| LC16YD3 | *026-1193-203 | LC22WT3 | *080-0535-203 | LC33YN2 | *130-0933-003 |
| LC17BD3 | 203-0114-203 | LC22YD3 | 080-0513-203 | LC34CN2/DO2 | *271-0171 |
| LC17BN3 | 203-0134-203 | LC22YN3 | *080-0533-203 | LC34CN2/SO2 | *271-0272 |
| LC17CD3 | 203-0117-203 | LC23BD3 | 209-0114-203 | LC34EN2/DO2 | *271-0111 |
| LC17CN3 | *203-0137-203 | LC23BN3 | 209-0134-203 | LC34EN2/EN2 | *271-3111 |
| LC17GD3 | 203-0112-203 | LC23CD3 | 209-0117-203 | LC34EN2/SO2 | *271-0212 |
| LC17GN3 | 203-0132-203 | LC23CN3 | *209-0137-203 | LC35BN2 | 128-0934-003 |
| LC17RD3 | 203-0111-203 | LC23GD3 | 209-0112-203 | LC35BT2 | 128-0974-003 |

* Can be used with Based LED Replacement Lamps

LC and LH, MS Military Designations to Dialight Part Numbers

MILITARY SPECIFICATION:

MIL-DTL-3661C-Lampholders, Indicator Lights, Indicator-Light Housings, Indicator-Light Lenses

| MILITARY DESIGNATION | DIALIGHT PART NO. | MILITARY DESIGNATION | DIALIGHT PART NO. | MILITARY DESIGNATION | DIALIGHT PART NO. |
|----------------------|-------------------|----------------------|-------------------|----------------------|--------------------|
| LC35CN2 | *128-0937-003 | LH88/1 | 366-8836-09-553 | MS18236-1RN | 507-5338-0931-630 |
| LC35GN2 | 128-0932-003 | LH88/2 | 366-8864-09-523 | MS18236-1WT | 507-5338-0935-630 |
| LC35GT2 | 128-0972-003 | LH89/1 | 367-8430-09-503 | MS18236-1YN | 507-5338-0933-630 |
| LC35RN2 | *128-0931-003 | LH90/1 | 370-8738-504 | MS18236-2CN | 507-5337-0937-670 |
| LC35RT2 | 128-0971-003 | LH90/2 | 371-8738-14-504 | MS18236-2RN | 507-5337-0931-670 |
| LC35WT2 | 128-0975-003 | LH90/3 | 371-8760-14-504 | MS18236-2WT | 507-5337-0935-670 |
| LC35YN2 | *128-0933-003 | LH92/1 | 271-8430-702 | MS18236-2YN | 507-5337-0933-670 |
| LC35YT2 | 128-0973-003 | LHC82/1BT2 | 252-9951-0974 | MS18237-1CN | 507-5338-1537-630 |
| LC36BD2 | 160-0114-203 | LHC82/1CN2 | 252-9951-0937 | MS18237-1RN | 507-5338-1531-630 |
| LC36CD2 | 160-0117-203 | LHC82/1GT2 | 252-9951-0972 | MS18237-1WT | 507-5338-1535-630 |
| LC36GD2 | 160-0112-203 | LHC82/1RT2 | 252-9951-0971 | MS18237-1YN | 507-5338-1533-630 |
| LC36RD2 | 160-0111-203 | LHC82/1WT2 | 252-9951-0975 | MS18237-2CN | 507-5337-1537-670 |
| LC36YD2 | 160-0113-203 | LHC82/1YT2 | 252-9951-0973 | MS18237-2RN | 507-5337-1531-670 |
| LC37BD2 | 161-0114-203 | MS18235-1BT | 507-3909-1474-600 | MS18237-2WT | 507-5337-1535-670 |
| LC37CD2 | 161-0117-203 | MS18235-1CN | 507-3909-1437-600 | MS18237-2YN | 507-5337-1533-670 |
| LC37GD2 | 161-0112-203 | MS18235-1GT | 507-3909-1472-600 | MS18238-1 | 507-6022-1437-600 |
| LC37RD2 | 161-0111-203 | MS18235-1RT | 507-3909-1471-600 | MS18238-2 | 507-6023-1437-600 |
| LC37YD2 | 161-0113-203 | MS18235-1WT | 507-3909-1475-600 | MS25256-2 | *162-8430-0933-502 |
| LH73/1 | 359-8430-09-502 | MS18235-1YT | 507-3909-1473-600 | MS25256-4 | 162-8430-0932-502 |
| LH73/2 | 362-8430-09-702 | MS18235-2BT | 507-3914-1474-600 | MS25256-6 | *162-8430-0931-502 |
| LH74/1 | 361-8836-09-552 | MS18235-2CN | 507-3914-1437-600 | MS25256-8 | *162-8430-0937-502 |
| LH74/2 | 361-8864-09-522 | MS18235-2GT | 507-3914-1472-600 | MS25256-10 | 162-8430-0975-502 |
| LH74/3 | 364-8836-09-752 | MS18235-2RT | 507-3914-1471-600 | MS25256-12 | 162-8430-0934-502 |
| LH74/4 | 364-8864-09-722 | MS18235-2WT | 507-3914-1475-600 | MS25257-2 | 137-8836-0933-552 |
| LH76/1 | 373-0408-01-273 | MS18235-2YT | 507-3914-1473-600 | MS25257-4 | 137-8836-0931-552 |
| LH76/2 | 373-0463-01-223 | MS18235-3BT | 507-3918-1474-600 | MS25257-6 | 137-8836-0937-552 |
| LH76/3 | 373-0410-01-203 | MS18235-3CN | 507-3918-1437-600 | MS25446-2** | 252-9951-0974 |
| LH77/1 | 377-0408-11-273 | MS18235-3GT | 507-3918-1472-600 | MS25446-3** | 252-9951-0972 |
| LH77/2 | 377-0463-11-223 | MS18235-3RT | 507-3918-1471-600 | MS25446-4** | 252-9951-0971 |
| LH77/3 | 377-0410-11-203 | MS18235-3WT | 507-3918-1475-600 | MS25446-5** | 252-9951-0975 |
| LH79/1 | 378-3404-01-203 | MS18235-3YT | 507-3918-1473-600 | MS25446-6** | 252-9951-0973 |
| LH80/1 | 378-3402-01-203 | MS18236-1CN | 507-5338-0937-630 | MS25446-7** | 252-9951-0937 |

** See LHC82/1

MILITARY SPECIFICATION:

MIL-L-7806-Light, Panel Plastic Plate Lighting

| | | | | | |
|-------------|--------------------|-------------|--------------------|-------------|--------------------|
| MS25010A11A | *270-1930-0111-702 | MS25010B11A | *270-1830-0111-702 | MS25010C11B | *271-8430-0111-702 |
| MS25010A12A | *270-1930-0171-702 | MS25010B12A | *270-1830-0171-702 | MS25010C12B | *271-8430-0171-702 |
| MS25010A13A | *270-1930-3111-702 | MS25010B13A | *270-1830-3111-702 | MS25010C13B | *271-8430-3111-702 |
| MS25010A14A | CONSULT FACTORY | MS25010B14A | CONSULT FACTORY | MS25010C14B | *271-8430-3171-702 |
| MS25010A15A | *270-1930-0212-702 | MS25010B15A | *270-1830-0212-702 | MS25010C15B | *271-8430-0212-702 |
| MS25010A16A | *270-1930-0272-702 | MS25010B16A | *270-1830-0272-702 | MS25010C16B | *271-8430-0272-702 |

MILITARY SPECIFICATION:

MIL-L-7961C-Light, Indicator, Press-to-Test

| | | | | | |
|-----------|--------------------|------------|--------------------|-----------|-------------------|
| MS25041-1 | *801-1030-0337-504 | MS25041-7 | 800-1030-0332-504 | MS25331-3 | 804-1710-0332-504 |
| MS25041-2 | *801-1030-0331-504 | MS25041-8 | *800-1030-0333-504 | MS25331-4 | 804-1710-0333-504 |
| MS25041-3 | 801-1030-0332-504 | MS25041-10 | 801-1030-0334-504 | MS25331-5 | 803-1710-0337-504 |
| MS25041-4 | *801-1030-0333-504 | MS25041-11 | 800-1030-0334-504 | MS25331-6 | 803-1710-0331-504 |
| MS25041-5 | *800-1030-0337-504 | MS25331-1 | 804-1710-0337-504 | MS25331-7 | 803-1710-0332-504 |
| MS25041-6 | *800-1030-0331-504 | MS25331-2 | 804-1710-0331-504 | MS25331-8 | 803-1710-0333-504 |

*Can be used with Based LED Replacement Lamps.